Installation Notes

Product: **Balance Shaft Delete Kit**

Date: **8-21-26**



! You have to properly seal the oil passage or it will starve the center mains and rods !
Failed balance shaft bearings like this one cause
low oil pressure to #2 and #3 rods and center Main bearing



Using the factory tool to move the bearing over 5.5mm. It has this colored ring that makes measurement easy. This could also be accomplished with a universal 44mm cam bearing tool.





Check
that the oil passage is blocked off either with compressed air or a light or both. It reaches up from the center main bearing and intersects the balance shaft bearings you can just see in the top of these images.



Taliaferro Imports, Inc.
525 N Prince Lane
Springfield, MO 65802 USA
417.831.7222 M-F 8-5 CST
Catalog@**GenuineSaab.com**

No Reproduction Permitted

Know the Dangers, Don't Learn by Accident!

If in doubt, consult a professional.